

MATERIAL SAFETY DATA SHEET

SPLICED VENEER

EdgeCo, Inc.

194 Candlewood Road- Bay Shore – New York – 11706
Phone 800 644 6449 www.edgecoinc.com Fax 631 434 2775

PRODUCT: Hardwood veneer
Component: Wood dust
Component: Urea-Formaldehyde condensate
SYNONYMS: None
CAS. NO.: None
DESCRIPTION: Particles generated by any manual or mechanical cutting or abrasion process performed on wood.

PHYSICAL DATA

Boiling Point.....Not Applicable
Specific Gravity.....Variable
(Dependent on wood species
and moisture content).
Vapor Density.....Not Applicable
% Volatiles by Volume...Not Applicable
Melting Point.....Not Applicable
Vapor Pressure.....Not Applicable
Solubility in H²O (% by wt.)...Insoluble
Evaporation Rate –
(Butyl Acetate=1)...Not Applicable
pH.....Not Applicable
Appearance & Odor...Light to dark colored
granular solid. Color and odor are dependent
on the wood species and time since dust was generated

FIRE & EXPLOSION DATA

Flash Point.....Not Applicable
Autoignition Temperature...Variable
(typically 400-500°F)
Explosive Limits in Air...40 grams/m³ (LEL)
Extinguishing Media.....Water, CO₂, Sand
Special Fire Fighting Procedures.....Wet down
with water. Wet down wood dust to reduce likelihood
of ignition or dispersion of dust into the air. Remove
burned or wet dust to open area after fire is extinguished.
Unusual Fire & Explosion Hazard.....Strong to
severe explosion hazard. (if wood dust
“cloud” contacts an ignition source.)

HEALTH EFFECTS DATA

Component: Wood Dust
Exposure Limit.....ACGIH TLV ®
TWA – 5.0mg/m³ STEL_(15 min.) – 10 mg/m³,
(certain hardwoods such as beech and oak) OSHA
PEL: TWA (see footnote 1) – (total dust) –
15.0mg/m³ (respirable factor) – 5.0mg/m³
Skin & Eye Contact.....Eye Irritation & Allergic
Contact Dermatitis. (Wood dust can cause eye
irritation. Various species of wood dust can elicit
allergic contact dermatitis in sensitized individuals)
Ingestion.....Not Applicable
Skin Absorption.....Not known to occur
Inhalation.....May cause:
Nasal dryness, irritation & obstruction.
Coughing, wheezing, & sneezing: sinusitis
& prolonged colds have also been reported.
Chronic Effects.....May cause:
Wood dust, depending on species, may
cause dermatitis on prolonged repetitive
contact; may cause respiratory sensitization
and irritation. IARC classifies wood dust as
a carcinogen to humans (Group 1). This
classification is based primarily on IARC’s
evaluation of increased risk in the
occurrence of adenocarcinomas of the nasal
cavities and paranasal sinuses associated
with exposure to wood dust. IARC did not
find sufficient evidence to associate cancers
of the oropharynx, hypopharynx, lung,
lymphatic and hematopoietic systems,
stomach, colon, or rectum with exposure to
wood dust.

Component: Formaldehyde gas (emitted in small and diminishing quantities from Urea Formaldehyde resin glue).
CAS No.: 50-00-0
Exposure Limits: OSHA 0.3 ppm Ceiling
ACGIH TLV 0.3ppm@ .13 ft²/ft³
Skin & Eye Contact:..... Eye irritation and allergic contact dermatitis.
Inhalation:Nasal dryness and/or irritation.

REACTIVITY DATA

Conditions Contributing to Instability...Stable
(under normal conditions)
Incompatibility.....Avoid Contact with:
Oxidizing agents, drying oils and flame.
Product may ignite at temperatures in excess of 400°F.
Hazardous Decomposition Products.....
Thermal-oxidative degradation of wood produces: irritating & toxic fumes and gasses, including CO, aldehydes and organic acids.
Conditions Contributing to Polymerization....
Not Applicable

PRECAUTIONS AND SAFE HANDLING

Eye Contact.....Avoid
Skin Contact.....Avoid
Repeated or prolonged contact with skin. Careful bathing and clean clothes are indicated after exposure.
Inhalation.....Avoid
Prolonged or repeated breathing of wood dust in air.
Oxidizing agents and drying oils.....
Avoid contact
Open Flame.....Avoid

GENERALLY APPLICABLE CONTROL MEASURES

Ventilation.....Provide:
Adequate general and local exhaust ventilation to maintain healthful working conditions.
Safety Equipment.....Wear goggles or safety glasses. Other protective equipment such as gloves and approved dust respirators may be needed depending upon dust conditions.

EMERGENCY AND FIRST AID PROCEDURES

Eyes.....Flush with water to remove dust particles. If irritation persists, get medical attention.
Skin.....Get medical advice if a rash or persistent irritation or dermatitis occur, get medical advice where applicable before returning to work where wood dust is present.
Inhalation.....Remove to fresh air. If persistent irritation, severe coughing, breathing difficulties occur, get medical advice before returning to work where wood dust is present.
Ingestion.....Not applicable

SPILL/LEAK CLEAN-UP PROCEDURES

Recovery or Disposal.....Clean-up:
Sweep or vacuum spills for recovery or disposal; avoid creating dust conditions. Provide good ventilation where dust conditions may occur. Place recovered wood dust in a container for proper disposal.

FOOTNOTE

Footnote 1: In *AFL-CIO v. OSHA* 965 F.2d 962 9 (11th Cir. 1992), the court overturned OSHA's 1989 Air Contaminants Rule, including the specific PEL's for wood dust that OSHA had established at that time. The 1989 PEL's were: TWA – 5.0 g/m³; STEL (15 min.) – 10.0 mg/m³ (ALL SOFT AND HARDWOODS, EXCEPT WESTERN RED CEDAR); **WESTERN RED CEDAR: TWA .5mg/m³**. Wood dust is now officially regulated as an organic dust under the Particulates Not Otherwise Regulated (PNOR) or Inert or Nuisance Dust categories at PEL's noted under the Health Effects Information section of this MSDS. However, a number of states have incorporated provisions of the 1989 standard in their state plans.